MassLynx Software Change Note #526

MassLynx Software Change Note #526 is for MassLynx Software Change Note #499.

This SCN supports NanoACQUITY system under MassLynx control. For details of nanoACQUITY operation refer to nanoACQUITY system documentation and release notes.

New Features

Support NanoAcquity as part of an LC system.

New Default pump method is required to support new fields in the XML file

MassLynx and Inlet editor should represent Nano flow rate correctly

Data Channel support

Fault Fixes

NONE

SCN 526 Installation Procedure

NOTE: MassLynx Software Change Note #499 must be installed before installing SCN526. If MassLynx Software Change Note #499 is reinstalled, SCN 526 must be reinstalled.

Users may require the MassLynx Software Change Note #499 CD during the SCN 526 installation.

Select Start->Run from the windows start menu and type:

<CD-Drive>:\Update <return>

Where, <CD-DRIVE> is the drive letter of the CDROM.

Follow the instruction of the setup program.

Updated Files

The following files will be copied onto your system when you install this Software Change Note:

WatersGIViews.dll

WatersGICtrl.dll

InletEditorConfigure.dll

InletKernelConfigure.dll

Default.wvhp



Default.w2200

Micromass Utilities/ICOP/Setup.exe

Micromass Utilities/ICOP/autorun.inf

Micromass Utilities/ICOP/ICOP.html

Micromass Utilities/ICOP/ACQUITY

December 2004